



Vehicle History Report #: 61184223
Report Date: May 3, 2025 | 1:44 p.m. EDT
Report Status: Complete

2013 VOLKSWAGEN JETTA BASE

Sedan | 4 Cylinders | Gas
3VW2K7AJ9DM296932
Country of Assembly: Mexico
Last Reported Odometer: 219,000 KM

Low
Kilometres™ >



No Accident/Damage Records Found



Last Registered In:
Ontario (Normal)



8 Service Records Found



No U.S. History Found



2 Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of May 03, 2025 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

3VW2K7AJ9DM296932

Vehicle History Report



Accident/Damage

✔ There are no accidents/damage reported on this vehicle.



Registration

✔ This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2017 Mar 15	83,631 KM	Economy Lube Oil & Filter Hamilton, Ontario, Canada	Vehicle serviced • Oil and filter changed
2017 Aug 1	93,529 KM	Economy Lube Oil & Filter Hamilton, Ontario, Canada	Vehicle serviced • Oil and filter changed
2018 Jan 19	104,902 KM	Economy Lube Oil & Filter Hamilton, Ontario, Canada	Vehicle serviced • Oil and filter changed
2019 Feb 28	125,175 KM	Economy Lube Oil & Filter Hamilton, Ontario, Canada	Vehicle serviced • Oil and filter changed
2020 Oct 16	134,408 KM	Volkswagen Richmond Hill Richmond Hill, Ontario, Canada	Vehicle serviced
2021 Aug 19	159,328 KM	Jiffy Lube #3489 Hanover, Ontario, Canada	Vehicle serviced • Maintenance inspection completed • Fluids checked • Oil and filter changed • Tire condition and pressure checked
2021 Oct 25	163,202 KM	Evan's Service Centre Hanover, Ontario, Canada	Vehicle serviced
2022 Jun 24	175,908 KM	KILSYTH AUTO SERVICE Owen Sound, Ontario, Canada	Vehicle serviced • Engine/powertrain computer/module checked • Exterior light bulb(s) replaced • Safety inspection performed



Open Recalls

3VW2K7AJ9DM296932

Recall #: 42G8 | REAR AXLE TRAILING ARM INLAY INSTALLATION Recall Date: 2015 Apr 07

Recall Description

This recall does not address a vehicle design or manufacturing defect; rather, the potential for this defect to be present can only occur after your vehicle has sustained damage to rear axle components as described below, and only if the damage is not properly repaired. Our records show that you are the owner of a vehicle that could possibly be affected by this issue...If your vehicle had sustained damage to rear axle components (from a rear or side-rear impact crash or after striking a high road obstacle while driving in reverse at higher speed) and a repair facility did not correctly diagnose/repair rear axle trailing arm damage, the durability of the trailing arm(s) could be reduced. This can lead to a sudden fracture of the trailing arm, a loss of vehicle control, and a crash without warning.

Remedy

Volkswagen will inspect the rear axle and install a sheet metal inlay on the rear axle trailing arms.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit [Volkswagen's website](https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html). (https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html)

Recall #: 37M2 | MICRO SWITCH Recall Date: 2019 Aug 27

Recall Description

Over time, a build up of silicate on the shift lever micro switch contacts can result in an isolation like layer that may be interpreted as an open micro switch. This open switch normally indicates that the shift lever is in P park position. If the build up happens, it may be possible to remove the key from the ignition switch without the shift lever being in the P park position because the system is unable to recognize that the vehicle is not in P park. This makes the vehicle noncompliant with FMVSS 114 Theft protection and rollaway prevention. If the ignition key is removed without the shift lever being in P Park position, there is a risk that the vehicle may roll away, resulting in a crash that could injure people and damage property.

Remedy

Install an additional switch and circuit board.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit [Volkswagen's website](https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html). (https://www.vw.com/en/owners-and-services/about-my-vehicle/recalls.html)



Stolen Vehicle Check

✔ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2013 Aug 23		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Vehicle colour noted as gray

3VW2K7AJ9DM296932

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2013 Nov 25		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal
2014 Dec 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2015 Mar 25	40,255 KM	Auto Auction	Auction Announcement	Vehicle sold
2015 Apr 7		VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 42G8
2015 Jun 2		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
2016 Jan 21		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Jan 30		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2017 Mar 15	83,631 KM	Economy Lube Oil & Filter Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2017 Aug 1	93,529 KM	Economy Lube Oil & Filter Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2018 Jan 19	104,902 KM	Economy Lube Oil & Filter Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2018 Feb 23		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Feb 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Feb 28	125,175 KM	Economy Lube Oil & Filter Hamilton, Ontario, Canada	Service Record	Vehicle serviced
2019 Aug 27		VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 37M2
2020 Mar 21	134,188 KM	Independent Source Ontario, Canada	Odometer reading	
2020 Oct 16	134,408 KM	Volkswagen Richmond Hill Richmond Hill, Ontario, Canada	Service Record	Vehicle serviced
2020 Nov 12		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal Vehicle colour noted as gray
2021 Jan 20		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as gray

3VW2K7AJ9DM296932

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2021 Aug 19	159,328 KM	Jiffy Lube #3489 Hanover, Ontario, Canada	Service Record	Vehicle serviced
2021 Oct 25	163,202 KM	Evan's Service Centre Hanover, Ontario, Canada	Service Record	Vehicle serviced
2022 Jan 20		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal Vehicle colour noted as gray
2022 Jun 24	175,908 KM	KILSYTH AUTO SERVICE Owen Sound, Ontario, Canada	Service Record	Vehicle serviced
2022 Jul 4		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal Vehicle colour noted as gray
2025 Apr 9	219,000 KM	Independent Source Ripley, Ontario, Canada	Odometer reading	
2025 Apr 23		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as gray



Questions? We're here to help.

Visit us at support.carfax.ca

CARFAX Canada Low Kilometres™ Badge

The CARFAX Canada Low Kilometres™ badge is based on the odometer information reported to CARFAX Canada. The CARFAX Canada Low Kilometres™ badge is available for vehicles registered in Canada that have accumulated, as reported to CARFAX Canada via odometer records, less than 18,000 kilometres per year from the beginning of September in the year prior to the vehicle's model year until the date that this report was generated.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2025 CARFAX Canada ULC. All rights reserved.

